



Photo 1 – Kindergarten Room 1



Photo 2 – Kindergarten Room 1  
Small sections of spalling concrete ceiling were observed on the ceiling.



Photo 3 – Kindergarten Room 1  
Small sections of spalling concrete ceiling were observed on the ceiling.



Photo 4 – Kindergarten Room 1  
A missing ceiling tile and condensate was dripping from the ceiling. Wet fiberglass pipe insulation was observed above the suspended ceiling.



Photo 5 – Kindergarten Room 1  
Mold growth was observed on the unit ventilator.



Photo 6 – Kindergarten Room 1  
Mold growth was observed on some of the plastic chairs.




Photo 7 – Kindergarten Room 1  
Mold growth was observed on the wooden door and metal frame.




Photo 8 – Kindergarten Room 1  
Mold growth was observed on the wooden door and metal frame.




Photo 9 – Kindergarten Room 1  
Mold growth was observed on the wooden built-in cabinetry and coat cubby.




Photo 10 – Kindergarten Room 1  
Mold growth was observed on the wooden built-in cabinetry and coat cubby.



Photo 11– Kindergarten Room 1  
Mold growth was observed on the wooden built-in cabinetry and coat cubby.



Photo 12 – Kindergarten Room 1  
Mold growth was observed on the metal storage cabinet.



Photo 13 – Kindergarten Room 2  
Missing ceiling tiles were observed.



Photo 14 – Kindergarten Room 2



Photo 15 – Kindergarten Room 2



Photo 16 – Kindergarten Room 2

Mold growth was observed on the built-in wooden cabinetry and coat cubby.



Photo 17 – Kindergarten Room 2  
Mold growth was observed on the built-in wooden cabinetry and coat cubby.



Photo 18 – Kindergarten Room 2  
Mold growth was observed on the built-in wooden cabinetry and coat cubby.



Photo 19 – Kindergarten Room 2  
Mold growth was observed on the built-in wooden cabinetry and coat cubby.



Photo 20 – Kindergarten Room 2  
Mold growth was observed on the built-in wooden cabinetry and coat cubby.



Photo 21 – Kindergarten Room 2  
Mold growth was observed on the built-in wooden cabinetry and coat cubby.




Photo 22 – Kindergarten Room 2  
Mold growth was observed on the teacher's desk.



Photo 23 – Kindergarten Room 2  
Mold growth was observed on a ceiling tile.



Photo 24 – Kindergarten Room 2  
Mold growth was observed on cabinetry.



Photo 25 – Kindergarten Room 2  
Mold growth was observed on the sink cabinet.



Photo 26 – Kindergarten Room 2  
A leak was observed under the sink.



Photo 27 – Kindergarten Room 2 Closet  
Mold growth was observed on the radiator cover and chilled water was passing through the heating convector.



Photo 28 – Kindergarten Room 2 Closet  
Mold growth was observed on the plastic chairs.



Photo 29 – Kindergarten Room 3



Photo 30 – Kindergarten Room 3

Mold growth was observed on the wooden built-in cabinetry and coat cubby.




Photo 31 – Kindergarten Room 3  
Mold growth was observed on the wooden built-in cabinetry and coat cubby.



Photo 32 – Kindergarten Room 3  
Mold growth was observed on the plastic chairs.



Photo 33 – Kindergarten Room 3  
Mold growth was observed on the plastic chairs.



Photo 34 – Kindergarten Room 3  
The return air tray was not seated properly and no air filters were observed inside this unit.



Photo 35 – Kindergarten Room 3  
Outdoor air intake open to the interior from construction activity.



Photo 36 – Kindergarten Room 3  
During the construction activity classrooms were exposed to outdoor air for periods of time during evaluation of the lintel and replacement of the brick.

Photo 37 – Kindergarten Room 3



Photo 38 – Kindergarten Room 3

A piece of flashing was hanging above the Kindergarten doorway.



Photo 39 – Kindergarten Room 3

Daylight visible through the back of the unit ventilator.



Photo 40 – Kindergarten Room 3  
No air filters were observed in this unit.



Photo 41 – Kindergarten Room 3  
The condensate drip pan was missing. Condensate was dripping on the floor.



Photo 42 – Front of Building  
Construction activity in progress