



Photo 1 – Room 102

A missing section of floor tile was observed in front of the unit ventilator.



Photo 2 – Room 102

Water stained ceiling tiles were observed above the unit ventilator.



Photo 3 – Room 102
Mold growth was observed on the wallboard to the right of the unit ventilator.



Photo 4 – Room 102
Elevated moisture content was detected on the wallboard below the section of mold growth.



Photo 5 – Hallway outside Room 106
Condensate was leaking from a section of duct work located above the suspended ceiling.



Photo 6 – Hallway outside Room 106
Condensate was leaking from a section of duct work located above the suspended ceiling.



Photo 7 – IMC



Photo 8 –IMC

Mold growth was observed on sections of the exposed duct work.



Photo 9 – IMC
Mold growth was observed on sections of the exposed duct work.



Photo 10 – IMC
Mold growth was observed on sections of the exposed duct work.



Photo 11– IMC
Mold growth was observed on sections of the exposed duct work.



Photo 12 – IMC
Suspect mold growth was observed on the work stations below the center supply branch.



Photo 13 – IMC

Elevated moisture content was detected on the work stations below the center supply branch.



Photo 14 – IMC Office 136

Water stained and moldy ceiling tiles were observed.



Photo 15 – IMC 134 MDF Room
Water was leaking from the condensate pump.



Photo 16 – IMC 134 MDF Room
Water was leaking from the condensate pump.



Photo 17 – IMC 134 MDF Room
A delaminated section of floor tile was observed from the leaking condensate pump.