



Photo 1 – Room 106



Photo 2 – Room 106

Moisture damaged paint and plaster was observed around the windows.



Photo 3 – Room 106
Paint and plaster debris was observed on the window sills.



Photo 4 – Room 106
Moisture damaged paint and plaster was observed around the windows.



Photo 5 – Room 104



Photo 6 – Room 104

A minimum amount of efflorescence was observed around 2 windows.



Photo 7 – Room 103

A minimum amount of efflorescence was observed around the windows on the right.



Photo 8 – Room 102

Moisture damaged paint and plaster was observed around 5 windows.




Photo 9 – Room 102
Moisture damaged paint and plaster was observed around 5 windows.



Photo 10 – Room 102
Moisture damaged paint and plaster was observed around 5 windows.



Photo 11– East Stairwell

A moisture damaged section of the ceiling was observed from a roof leak that was stabilized.



Photo 12 – East Stairwell

moisture damaged section of the ceiling was observed from a roof leak that was stabilized.



Photo 13 – Room 202

Moisture damaged paint and plaster was observed around the windows and in the corner of the room. Paint and plaster debris was observed on the windows sills.



Photo 14 – Room 202

Moisture damaged paint and plaster was observed around the windows and in the corner of the room. Paint and plaster debris was observed on the windows sills.



Photo 15 – Room 202 Closet
Flaking paint was observed on the ceiling of the closet.



Photo 16 – Room 202 Closet
Staining was observed on the ceiling from a leak that was stabilized.



Photo 17 – Room 203

Flaking paint and staining was observed on the ceiling from a leak that was stabilized.



Photo 18 – Room 203

Moisture damaged paint and plaster was observed around the right windows.



Photo 19 – Hallway outside Room 207
Flaking paint and staining was observed on the ceiling from a leak that was stabilized.



Photo 20 – Room 204
Moisture damaged paint and plaster was observed around 2 windows.



Photo 21 – Room 204
Paint and plaster debris was observed on one of the window sills.



Photo 22 – Room 205
Flaking paint and staining was observed on the ceiling from a leak that was stabilized.



Photo 23 – Room 205
Moisture damaged paint and plaster was observed around a window.



Photo 24 – Room 206
Flaking paint and water staining was observed on the ceiling from a leak that was stabilized.



Photo 25 – Room 206
Moisture damaged paint and plaster was observed around 2 windows.



Photo 26 – Room 206
Moisture damaged paint and plaster was observed around 2 windows.



Photo 27 – Room 206
Moisture damaged paint and plaster was observed around 2 windows.



Photo 28 – Room 207
Flaking paint and water staining was observed on the ceiling from a leak that was stabilized.



Photo 29 – Hallway outside Room 207
Flaking paint and water staining was observed on the ceiling.



Photo 30 – Counselor's Office (2nd floor)
Moisture damaged plaster was observed on the upper wall section.



Photo 31 – Nurse's Office
Flaking paint was observed above 1 window.