



Photo 1 – Main Entrance
A steam leak was observed on the east side of the main entrance.



Photo 2 – Room 101



Photo 3 –Room 101

A steam leak in the crawlspace below impacted the hardwood flooring in the corner of the room.



Photo 4 –Room 101

The asbestos containing pipe riser will need to be removed to allow for repairs.



Photo 5 – Room 101



Photo 6 – Room 108

A steam leak occurred on the riser between the crawlspace and radiator.



Photo 7 – Room 108

A steam leak occurred on the riser between the crawlspace and radiator. The wooden baseboard was impacted by the steam.



Photo 8 – Room 103

The hardwood flooring was impacted by a steam leak from this radiator.



Photo 9 – 1st Floor Hallway
The compressor for the hydration station was making a very loud noise and was unplugged.