



Photo 1 – Gymnasium



Photo 2 – Gym Office

Water stained and missing ceiling tiles were observed.



Photo 3 – 2<sup>nd</sup> Floor Hallway (Race Street)  
Water stained ceiling tiles were observed.



Photo 4 – Room 214  
Water staining was observed on the ceiling tiles and wallboard.



Photo 5 – 2<sup>nd</sup> Floor Hallway  
The light trim was hanging below the ceiling.



Photo 6 – Room 107  
Water stained and missing ceiling tiles were observed.



Photo 7 – Room 108  
A missing ceiling tile was noted.



Photo 8 – Room 108  
A water line was repaired; however, the lines need to be insulated.



Photo 9 – Room 109  
Special Needs Room



Photo 10 – Room 109  
Particulate accumulation was observed on the relief grilles.



Photo 11– Room 109  
A water stained ceiling tile was observed.